Photo Album for
Cedar Hill Fire Protection District MO
Job # 42616
W/O # 33165501
October 31, 2026

Since the last report, the chassis began preparations for fire service, and the pump house began the paint process. The body was in staging. Next week the chassis should continue with chassis prep, and the pump house may finish the paint process. The body should begin to receive trim and wiring harnesses.



DSC00137



DSC00138



DSC00139



DSC00140

Find us on
Facebook



DSC00141



DSC00142



DSC00143



DSC00144

Find us on Facebook



DSC00145



DSC00146



DSC00147



DSC00148

Find us on Facebook



DSC00149



DSC00150



DSC00151



DSC00152

Find us on Facebook



DSC00153



DSC00154



DSC00320



DSC00321

Find us on Facebook



DSC00322



DSC00323

Find us on Facebook