Photo Album for
Cedar Hill Fire Protection District MO
Job # 42616
W/O # 33165501
November 7, 2026

This week the chassis was unavailable for photos, and the pump house began final pump assembly. The body was in staging. Next week the chassis should continue with chassis prep, and the pump house should finish final pump assembly. The body should begin to receive trim and wiring harnesses.




DSC00105



DSC00106



DSC00107



DSC00108

Find us on Facebook



DSC00109



DSC00110



DSC00111



DSC00112

Find us on Facebook



DSC00256



DSC00257



DSC00258



DSC00259

Find us on Facebook