




Photo Album for Goodview Fire and Rescue MN

Job # 44826

W/O # 34651079

August 15, 2026

This week the cab was fabricated and began the paint process, and the fire pump was joined with the pump house structure. The body finished with paint. Next week the cab should continue with paint, and the pump house could begin the paint process. The body may begin to receive trim and wiring harnesses.



DSC00027



DSC00028



DSC00029



DSC00030



DSC00126



DSC00127



DSC00128



DSC00129



DSC00130



DSC00131



DSC00210



DSC00211



DSC00212



DSC00213