


Photo Album for Goodview Fire and Rescue MN

Job # 44826

W/O # 34651079

August 22, 2026

This week the cab was unavailable for photos and the pump house began the paint process. The body was back in paint. Next week the cab and pump house should finish the paint process and the body may finish with paint.





DSC00117



DSC00118



DSC00119



DSC00120



DSC00121



DSC00122



DSC00123



DSC00124