Photo Album for
Goodview Fire and Rescue MN
Job # 44826
W/O # 34651079
October 10, 2026

Since the last report, the cab was mounted and the pump house was in staging (no photos). The body began to receive trim and wiring harnesses. Next week the pump house and body should be mounted.



DSC00093



DSC00094



DSC00095



DSC00096


Find us on Facebook



DSC00097



DSC00098



DSC00099



DSC00100

Find us on Facebook