Photo Album for
Goodview Fire and Rescue MN
Job # 44826
W/O # 34651079
October 17, 2026

This week the chassis continued with chassis prep and the pump house was in staging. The body continued to receive trim and wiring harnesses. Next week the pump house and body should be mounted.



DSC00228



DSC00229



DSC00230



DSC00231

Find us on Facebook



DSC00232



DSC00233



DSC00234



DSC00235

Find us on Facebook



DSC00236



DSC00237



DSC00238



DSC00239

Find us on Facebook