




Photo Album for Goodview Fire and Rescue MN

Job # 44826

W/O # 34651079

August 29, 2026

This week the cab, pump house and body finished with paint. Next week the cab may begin to receive trim and wiring harnesses and the pump house may begin final pump assembly. The body may begin to receive trim and wiring harnesses.



DSC00087



DSC00088



DSC00112



DSC00113



DSC00114



DSC00115



DSC00116



DSC00117



DSC00118



DSC00119