




Photo Album for Goodview Fire and Rescue MN

Job # 44826

W/O # 34651079

September 12, 2026

Since the last report the cab, pump house and body were in staging. Next week the cab should begin to receive trim and wiring harnesses and the pump house should begin final pump assembly. The body should begin to receive trim and wiring harnesses.



DSC00236



DSC00237



DSC00238



DSC00239



DSC00240



DSC00241



DSC00242



DSC00243



DSC00244



DSC00245