




Photo Album for Goodview Fire and Rescue MN

Job # 44826

W/O # 34651079

September 19, 2026

This week the cab, pump house and body were in staging. Next week the cab should begin to receive trim and wiring harnesses and the pump house should begin final pump assembly. The body should begin to receive trim and wiring harnesses.



DSC00191



DSC00192



DSC00193



DSC00194



DSC00195



DSC00196



DSC00207



DSC00208



DSC00209



DSC00210